## Oil Field Environmental Incident Summary

Incident: 20150210171002 **Date/Time of Notice:** 02/10/2015 17:10 Responsible Party: SLAWSON EXPLORATION COMPANY, INC. SLAWSON EXPLORATION COMPANY, INC. Well Name: IRONBANK 5-14-13TFH Field Name: STOCKYARD CREEK Well File #: 28053 Date Incident: 2/10/2015 Time Incident: 01:15 Facility ID Number: **WILLIAMS** Twp: 154 **Rna**: 99 Sec: 14 Qtr: County: Location Description: Submitted By: Ray Gorka Received By: Ray Gorka Contact Person: **1675 BROADWAY STE 1600** DENVER, CO 80202 General Land Use: Cultivated Affected Medium: Well/Facility Soil 2957 Feet Distance Nearest Occupied Building: 2957 Feet Distance Nearest Water Well: Type of Incident: Valve/Piping Connection Leak Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Spilled Units Recovered Units Followup **Units** 2 Oil 2 Barrels Barrels **Brine** Other **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: none Areal Extent: ......

## Potential Environmental Impacts:

none

## Action Taken or Planned:

well shut in and clean up operations will commence and finish when road travel is safer, as freezing rain has made a hazard of roads in the area.

Wastes Disposal Location: licensed disposal facility

Agencies Involved:

## **Updates**

Date: 2/11/2015 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.